SWC701 v0.98.2281

Subject	Notes

NEW

Special controllers for Russia

To the program have been added the following special controllers for Russia:

Xte600S3
Xse600S3
Xte602S1
Xse602S1
Xte611S2

DRU614C2

To the program has been added the support of controller DRU614C2

FTC738

To the program has been added the support of controller FTC738

TRS100

The support has been added of the controller TRS100 (OEM version of controller FTC738

URX918

To the program has been added the support of controller URX918.

XCO428

The support has been added of controller XCO 428.

AMENDMENTS & IMPROVEMENTS

RTB645 & RTB645S1

The following problem has been resolved: an erroneous display of the status of the "Special program" switch status on the Synoptic.

SWC701 –Settings

For the GSM modems has been added the option of setting the following types of service:

Non transparent 14400 bps (V.34)
Non transparent   9600 bps (V.110)
Non transparent 14400 bps (V.110)

SWC701 – Record of events

When you send a "Historic sent" file of the type "A historic sent file", in the "Description" column of the "Events register" is displayed also the description of the "Historic sent" file.

Subject	Notes

UAC328

Improvements have been made to the display of the "Configuration times" page.

VAV614

The "Description function" which may be inserted in the "Details" page is now saved correctly.

XTR628

The following small problem has been resolved: the cutting off of the definitions of the inputs on the "Alarms & measurements" page.

XTU644

The following problem has been resolved; under certain conditions, in the display of temperatures of the sensors, dashes appeared instead of the temperature.

The following problem has been resolved: erroneous display of the season switching status.

_____