SWC701 v0.98.2360

Product   ***Notes***

LATEST

DRU614C3

> To the program has been added the support of controller DRU614C3.

XTE600S1, XSE600S1

> To the program have been added the support of controllers XTE600S1 & XSE600S1.

XTP600, XSP600

> To the program have been added the support of controllers XTP600 & XSP600.

AMENDMENTS & IMPROVEMENTS

CMC328

> The option of running the MET controllers with Automatic speed has been added.
> A mode has been added which permits disabling the automatic research of the communication speed with an Mbus device.

MRL608

> The problem of displaying the correct season on the alarms and measurements page of the individual zones has been resolved.
> A problem of display ordered by zones in the events recorder has been resolved.
> The names of the three relays regarding the activation of the functions are now associated with the details of the functions.

RTBX10, RTBX11

> A problem regarding the 'Local correction of room T' on the 'Settings' page has been resolved.

SWC701 – Modem

> In the standard configuration of the MPD412 modem the data compression has been disabled.
> Support of modem MCV712 has been added.

Product	Notes
UCO318	The problem of setting the delay end alarm for K switch has been resolved.
URX918	As from version 5 of the controller firmware there has been added the display of the messages on the recorder page.
XTT618	As from version 16 of the firmware controller XTT618 administers the password for readout only via Telemanagement; the setting range of the parameter 'Reduction secondary flow T' has been increased.
XTT618S1	As from version firmware 2 has been added the readout only password for Telemanagement and changes have been made to the setting range of the parameter 'Reduction T secondary flow' on the 'Configuration controller' page.