SWC701 v1.11.2740

Subject	Notes
NEW	
TRS100C1	Software updated to support device TRS100C1.
XCC618C1	Software updated to support device XCC618C1.
XCC638C1	Software updated to support device XCC638C1.
XTC638C1	Software updated to support device XTC638C1.

CHANGES AND IMPROVEMENTS

CSV328

Solution of a problem preventing the viewing of object animations in synoptics for outputs W1 and W2

DSE600, XSE600, XSE600C1, XSP600

Solution of a problem that in models DSE600, XSE600, XSE600, XSE600C1, XSP600 prevented the value "C-Ring temperature increase on desired boiler temperature" from being adjusted in "Boiler Setting", under "Heating Setting".

DXE600C1, DTE600C1

Solution of a problem with the erroneous setting of the special period with priority over other programs, which prevented correct data on the start and end month and day of the period from being sent to devices DTE600C1 and DSE600C1.

FTC738, TRS100, XTC638, FTC738C1, XCC638, XCC618, TRS100C1

Solution of a problem preventing the viewing of parameter "Boiler loading pump control if boiler/manifold T > boiler T" on page "Settings/Hot water" with device firmware versions higher than 6.

Also, with device firmware versions higher than 7, on the Alarms and Measures page, the Desired Boiler T was not viewed with C-Ring configuration set to BOILER PRIORITY of BOILER + ZONES PRIORITY, or BOILER SECONDARY, despite Boiler Power being set to Shared on the boiler setting page.

IET73X

Friday 25 March 2011

Option added of inserting units of measure in auxiliary input details

IET7XX, DLP738, UCT328, UCT328C1

In the event of automatic calls at fixed times, with updating of the zone number if not synchronised, the zone number, even when not used by the device, was always updated, and therefore the reading was carried out of all data following the synchronisation of the zone number.

SWC701 - GSM724

Default speed of the serial port for GSM724 modem set to 460800bps, and modem serial speed detection scan is also carried out for speeds 230400bps, 460800bps, and 921600bps.

SWC701 – Background Image

"strPathFileBackgroundimage" item added to SWC.INI file, for insertion of image file address and name (in jpg, bmp, png, gif formats) for use as SWC701 background image

SWC701 – Events Record

Option added for an Administrator user with access only to certain groups of zones to view the events record for these groups.

SWC701 – Automatic reset from data send

If data was sent automatically and reset programmed, the events record failed to correctly display the date and time of the resetting.

SWC701 – Printouts

Solution of a printout problem with tabulators containing two or more lines.

SWC701 - TCP/IP

With TCP/IP connections, three attempts to connect to the destination Host can now be made before the connection is considered not valid.

XCC638, XCC618

Solution of an incorrect viewing problem which arose when "Master shutoff valve control" was set for input E2, while the synoptics displayed "Shared burner block".

XCO428

Solution of a problem with the incorrect printing of the SMS Configuration - Recent SMS texts received page.

Friday 25 March 2011

XPT678

In the normal use page, if a weekly program was set and the user pressed "View", the time ON/OFF status was not viewed correctly.

XTA624C1

In the normal use page the option has been added of setting a daily program for both heating and conditioning.

In the Settings page, main settings and adjustments, if season switch in the device configuration page, general, is set based on external temperature, it is now possible to insert season switch values and delays.

In the normal use page, status and measures alarm, as well as in the record, a status viewing option has been added, which indicates whether an annual program is in use, in addition to the operating mode.

XTE602C1, XSE602C1

In the normal use page, and in the time and periods page – weekly programmes, if a daily program higher than daily program 7 was set, the program was not viewed.

XTU614C1

Solution of a problem with the printing of the Settings – Main settings and adjustments page.